

Measurement Tips for your




Inside Mount or Outside Mount

- How you take your measurements will vary depending upon whether the shade fits within the window opening
- Inside mount fits within the window opening outside mount overlaps the window opening

"Rounding" Your Measurements


- Dimensions on the order form should be accurate to within 1/8"
- With outside mounts, round your measurements up or down to the nearest 1/8"
- With inside mounts, always round down to the nearest 1/8"
- Rounding up could result in a shade that is too wide to fit within the window opening.

Measuring for Inside Mounts



- Measure the width inside the window opening at the top, middle, and bottom
- Measure the height inside the window opening at the left, right, and center
- Order the narrowest width measurement and the longest height measurement
- Remember to round your measurements down to the nearest 1/8"
- Be sure the window opening is deep enough for the type of mounting bracket being used

Measuring for Outside Mounts



- Measure the desired width and height
- To minimize light leakage, it's recommended that the shade overlap the window opening at least 1 1/2" on each side
- At the bottom measure the height, take into account the mounting bracket

IMPORTANT TIP:

Outside mount shades will be fabricated from measurements provided by client from outside of bracket on **Left** to outside of bracket on **Right**. **Shades will be exactly the ordered width for outside mount.**

Qualified Installer: A qualified measurer/installer is always recommended for your custom window treatments. Window Interiors offers a network of qualified installers, available nationwide to our clients. Please call for details.



www.windowinteriors.com

1-800-654-9818

customerservice@windowinteriors.com